


2019-09-21 08:29:21




2019-09-21 08:29:21



FLIR0562.jpg FLIR E40 64509418

Korytarz techniczny szafa sterująca nr 11 - temperatura maksymalna ~43,9 C

2019-09-21 08:29:34




2019-09-21 08:29:34



Korytarz techniczny wentylator nr 10 - temperatura maksymalna ~32,5 C



2019-09-21 08:30:00



FLIR0566.jpg

FLIR E40

64509418

2019-09-21 08:30:00




FLIR0566.jpg

FLIR E40


64509418

Korytarz techniczny szafa sterująca nr 10 - temperatura maksymalna ~44,1 C

2019-09-21 08:30:07




2019-09-21 08:30:07




Korytarz techniczny wentylator nr 9 - temperatura maksymalna ~37,9 C

2019-09-21 08:30:36




2019-09-21 08:30:36



Korytarz techniczny szafa sterująca nr 9 - temperatura maksymalna ~43,3 C

2019-09-21 08:30:43



FLIR0572.jpg

FLIR E40

64509418

2019-09-21 08:30:43



FLIR0572.jpg


FLIR E40

64509418


Korytarz techniczny wentylator nr 8 - temperatura maksymalna ~27,8 C



2019-09-21 08:31:24




2019-09-21 08:31:24



Korytarz techniczny szafa sterująca nr 8 - temperatura maksymalna ~34,8 C

2019-09-21 08:31:29



FLIR0576.jpg

FLIR E40

64509418

2019-09-21 08:31:29



FLIR0576.jpg

FLIR E40


64509418

Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~47,5 C

2019-09-21 08:32:39




2019-09-21 08:32:39




Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~39,6 C

2019-09-21 08:32:59




2019-09-21 08:32:59



Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~59,9 C



2019-09-21 08:33:14




2019-09-21 08:33:14



Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~36,6 C

2019-09-21 08:33:28




2019-09-21 08:33:28



Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~35,8 C

2019-09-21 08:34:02



FLIR0586.jpg

FLIR E40

64509418

2019-09-21 08:34:02




FLIR0586.jpg

FLIR E40

64509418

Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~50,8 C

2019-09-21 08:34:14



FLIR0588.jpg

FLIR E40

64509418

2019-09-21 08:34:14



FLIR0588.jpg


FLIR E40

64509418

Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~38,1 C



2019-09-21 08:34:24



2019-09-21 08:34:24




FLIR0590.jpg

FLIR E40


64509418

Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~41,8 C

2019-09-21 08:34:40




2019-09-21 08:34:40




Korytarz techniczny nr 2 szafa rozdzielcza - temperatura maksymalna ~42,9 C

2019-09-21 08:39:34




2019-09-21 08:39:34




Płuczka - temperatura maksymalna ~44,6 C

2019-09-21 08:39:54




2019-09-21 08:39:54



Płuczka - temperatura maksymalna ~48,5 C



2019-09-21 08:40:14



FLIR0598.jpg

FLIR E40

64509418

2019-09-21 08:40:14




FLIR0598.jpg

FLIR E40


64509418

Płuczka - temperatura maksymalna ~46,1 C

2019-09-21 08:40:34




2019-09-21 08:40:34



Pluczka - temperatura maksymalna ~45,4 C

2019-09-21 08:41:20




2019-09-21 08:41:20




Rozdzielnica - temperatura maksymalna ~29,2 C

2019-09-21 08:46:16




2019-09-21 08:46:16




IKF - temperatura maksymalna ~24,2 C



2019-09-21 08:47:58




2019-09-21 08:47:58



IKF odkurzacz - temperatura maksymalna ~25,3 C

2019-09-21 08:51:16



FLIR0608.jpg

FLIR E40

64509418

2019-09-21 08:51:16




FLIR0608.jpg

FLIR E40

64509418

Szafa sterująca - temperatura maksymalna ~35,4 C

2019-09-21 08:51:39




FLIR0610.jpg

FLIR E40

64509418

2019-09-21 08:51:39




FLIR0610.jpg

FLIR E40

64509418

Szafa sterująca - temperatura maksymalna ~25,8 C

2019-09-21 08:53:06



FLIR0612.jpg

FLIR E40

64509418

2019-09-21 08:53:06



FLIR0612.jpg


FLIR E40

64509418


Szafa sterująca - temperatura maksymalna ~31,8 C



2019-09-21 08:53:31




2019-09-21 08:53:31




FLIR0614.jpg FLIR E40 64509418

Szafa sterująca - temperatura maksymalna ~27,7 C

2019-09-21 09:11:17




2019-09-21 09:11:17



Temperatura maksymalna ~8,8 C

2019-09-21 09:11:22



2019-09-21 09:11:22



Vecoplan - temperatura maksymalna ~7,0 C

2019-09-21 09:12:24



2019-09-21 09:12:24



FLIR0620.jpg


FLIR E40

64509418

Vecoplan - temperatura maksymalna ~8,1 C



2019-09-21 09:13:44




2019-09-21 09:13:44



Rozdrabniacz 9 B - temperatura maksymalna ~3,5 C

2019-09-21 09:14:04




2019-09-21 09:14:04




Rozdrabniacz 9 B - temperatura maksymalna ~22,9 C

2019-09-21 09:14:25




2019-09-21 09:14:25



Rozdrabniacz 9 A - temperatura maksymalna ~93,7 C

2019-09-21 09:14:49



2019-09-21 09:14:49




FLIR0628.jpg FLIR E40 64509418

Rozdrabniacz 9 A - temperatura maksymalna ~21,0 C



2019-09-21 09:15:39




2019-09-21 09:15:39



Taśma TR 10 - temperatura maksymalna ~15,7 C

2019-09-21 09:17:39




2019-09-21 09:17:39



FLIR0632.jpg FLIR E40 64509418

Taśma TR 16 - temperatura maksymalna ~18,9 C

2019-09-21 09:18:21




2019-09-21 09:18:21



FLIR0634.jpg FLIR E40 64509418

Taśma TR 16 - temperatura maksymalna ~18,7 C

2019-09-21 09:24:11



2019-09-21 09:24:11



Rozrywarka PPO - temperatura maksymalna ~32,8 C



2019-09-21 09:24:19




2019-09-21 09:24:19



Rozrywarka PPO - temperatura maksymalna ~37,6 C

2019-09-21 09:24:39




2019-09-21 09:24:39




Rozrywarka PPO - temperatura maksymalna ~5,8 C

2019-09-21 09:26:28




2019-09-21 09:26:28



Rozdzielnica RO-D - temperatura maksymalna ~32,9 C

2019-09-21 09:26:48




2019-09-21 09:26:48




Rozdzielnica RO-D - temperatura maksymalna ~34,3 C



2019-09-21 09:32:03




2019-09-21 09:32:03




Rozdzielnica RO-M - temperatura maksymalna ~14,8 C

2019-09-21 09:34:09




2019-09-21 09:34:09



Rozdzielnica plac manewrowy - temperatura maksymalna ~4,7 C

2019-09-21 09:35:57




2019-09-21 09:35:57




Rozdzielnica RO-G - temperatura maksymalna ~29,5 C



2019-09-21 09:39:12




2019-09-21 09:39:12



Rozdzielnica RO-B - temperatura maksymalna ~13,9 C



2019-09-21 09:41:45



2019-09-21 09:41:45




Rozdzielnica RO-W1 - temperatura maksymalna ~39,0 C

2019-09-21 09:46:54



2019-09-21 09:46:54



Rozdzielnica RO-2 - temperatura maksymalna ~14,4 C

2019-09-21 09:50:43



FLIR0666.jpg

FLIR E40

64509418

2019-09-21 09:50:43




FLIR0666.jpg

FLIR E40

64509418

Kotłownia - temperatura maksymalna ~34,5 C

2019-09-21 09:50:53



2019-09-21 09:50:53




Kotłownia - temperatura maksymalna ~71,7 C



2019-09-21 09:51:25




2019-09-21 09:51:25



Kotłownia - temperatura maksymalna ~58,0 C

2019-09-21 09:51:49



2019-09-21 09:51:49



Kotłownia - temperatura maksymalna ~74,0 C

2019-09-21 09:52:01




2019-09-21 09:52:01



Kotłownia - temperatura maksymalna ~49,3 C

2019-09-21 09:52:44




2019-09-21 09:52:44



Kotłownia - temperatura maksymalna ~48,0 C



2019-09-21 09:54:36



FLIR0678.jpg

FLIR E40

64509418

2019-09-21 09:54:36



FLIR0678.jpg

FLIR E40

64509418

Kotłownia - temperatura maksymalna ~32,7 C